



Maintenance Portfolio

Obre's promise to estate agencies:



We are always available at short notice



We say "YES" to every work-order



Fast job start & finish



We cover all England, every trade



Fast Feedback



We carry out tenant satisfaction survey



No signed contract, No commitment fees

Don't take our word for it, see some of our jobs in pages below

Apollo Drive, Wellingborough, Northamptonshire



New bath plug
removed from sealed



New outside stop valve




New bath plug

Calwell Drive, Maidenhead



Crack on roof before
repair work



During roof work



Repaired roof &
reapplied roof tar



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ground floor flat, Castle Road, London



New bath panel



New bathtub & new
tiles installed

Cavendish Mews, Heene Place, Worthing



Rusty old radiator



Old & new radiators



New radiator



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Claygate Hare Lane, Esher, Surrey



Old cartridge removed



Installed new cartridge



Testing new system


Coventry Road, Rugby, Warwickshire



Old snapped overflow pipe



The overflow pipe being installed



New cold-water tank overflow pipe installed



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing



Locksmiths

Residential
Projects

Hinkler Road, Southampton



Installed new PVC
Entrance door



Installed new Full
Bathroom




Installed new carpet &
new PVC window

Joyce Silver Court, Addington Road, Wellingborough



Adjusted & repaired
the PVC window



New door lock
installed



New mixer tap
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Kingfisher Drive, Maidenhead, Windsor




Testing boiler PCB

Longfellow Road, Worcester Park, London



Installed new bath,
tiling and sealed



New shower mixer tap



Full repointing of the
roof



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Matthias Court, Church Road, Richmond



New sink trap & waste connectors



New earth bonding & WM inlet hose



New under sink waste trap installed

Midleton Road, New Malden



Installed new condensing pipe



New boiler condensing trap installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Oaks Cottage, George Street, Wellingborough



Damaged PVC door lock




Installed new PVC door lock



Restoring old solid wooden door

Palace Road, London



New door lock installed



Slide door adjusted & tested



Installed new wardrobe shelve



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Savoy Close, Birmingham



Dust sheet installed
before painting



Newly painted
bedroom

Smallwood Road, London



Old fence



New fence installed



Garden left clean after
fence installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Southolm Street, Southwest, London



New PVC window
installed



New mixer taps
installed



New bath screen
installed

Tithelands, Harlow, Essex



Installed new PRV
valve



Tested boiler after re-
filling system



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Wilton Court, Westmount Close, London



Old boiler before
replacement



Installed new boiler

Woodland Rise, London



Installed 50cm wide fridge, with
new power point



Our operatives in full
PPE & mask



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Kings Road, Sudbury, Suffolk



Supplied & installed
new range cooker

Middleton Way, Crawley, West Sussex



New shower handle
railing installed



Shower thermostatic
valve repaired



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ennerdale Close, Sutton, London



New integrated freezer



Testing new fridge working

Ardmore Lane, Buckhurst Hill,
Essex

Brolly Works, Allison Street,
Birmingham



New electric hob
installed



Installed new sink &
mixer tap



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects

Chancellor's Road, London



Installed new bath
mixer taps

Fullers Mead, Harlow, Essex



New fire door installed

George Street, Rushden,
Northamptonshire



Installed a new shower



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects

Sheppeys, Haywards Heath,
West Sussex




New fence installed

Pavior Road, Nottingham




New shower room
door & rubber installed

Lancaster Ave, Mitcham,
Greater London



New fire door installed

Rawnsley Drive, Kenilworth,
Warwickshire



New garage door
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Meridian Court, Fernleigh Close, Croydon



Replacing bath
overflow waste pip



New trap installed

Cambie Crescent, Colchester



Supplied & installed
new oven

Mill Green, Congleton,
Cheshire



Supplied & installed new
toilet & lino flooring



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Dale Lodge, Shepherds Hill, Highgate



Painted living room
after repairs to walls

Turpin Close, Gainsborough,
Lincolnshire



Upgrade gas meter outlet
pipework from 15mm to 22mm

Boundary Close, Doncaster



Installed new window



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Barley Ponds Road, Ware, Hertfordshire



Gardening work



Repaired entrance wall

Bartok Close, Basingstoke



Repair to TV aerial

Broadfield Road, London



Installed new window
rubber and window hinge



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Admiral Way, Hyde, Greater Manchester



Isolation switch
replaced



Old faulty electrical
shower




New electrical shower
installed

Aria House, London



Adjusted & repaired
fallen wardrobe



Floor installation



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Birley Road, London



Installation of new
shower cartridge



New shower controls

Barnmead, Haywards Heath, West Sussex



Old element being
removed



New cylinder heating
element installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing




Locksmiths



Residential
Projects

Caernarvon Crescent, Milton Keynes

Chimney pointed &
new lead flashingNew ceiling following
painting

Porch roof skimmed

Brackenbury Gardens, London



Sealed shower room



Installed new bannister



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing



Locksmiths

Residential
Projects

Capitol Square, Surrey

Pipework boxing
(before)Pipework boxing
(after)

Church Hill Road, Surbiton

Installation of a new
expansion vessel

City House, London



Changing toilet parts



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing



Locksmiths

Residential
Projects

Carlington House, Normanton Road, London



New bathtub toilet &
sink installed



New tiles installed



Replacing pipework
inside boxing

Eastbourne Road, London



Installed bathtub
waste pipes



Installed new compression
boiler valves



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Garrick Close, London



Old water filter



New water filter
installed

Flaxley Close, Lincoln,
Lincolnshire



New vented MEGAFLO
cylinder installed

Fraser House, Clapham,
London



New trap installed under
bathtub



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Kelvin Gardens, Croydon



Applied silicon around
bathtub




Grouted all bathroom
tiles

Eggleton Drive, Wellingborough, Hertfordshire



New alternators
installed



New carpet fitted



New pump motor
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Garth Road, Morden, London



Old boiler before installation



New boiler being commissioned



Flue test on new boiler

Granville Chambers, Wellingborough



New toilet installation



New grouts on tiles



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing




Locksmiths

Residential
Projects


Kettering Road, Kettering, Northamptonshire



Cleaning drains following removal waste



Replaced soil down water pipe



Sealed with cement newly installed soil pipe

Kempsford Gardens, London



Damage caused by another contractor



New tiles installed, grouted & made good



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Lapwing Court, Wesham, Preston



Old expansion vessel
removed



New expansion vessel
installed



New pump fitted

Mildenhall Road, Birmingham, West Midlands



Damage in underground
waste pipe system



Unblocked manhole &
tested water running



Inspected all the
manholes around the
property



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Levy Close, Andover, Hampshire

Damaged tiles
replacedNew lead flashing
installed

London Road, Redhill, Surrey



Sealed full roof hips

Malthus Path, London



New toilet installed



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing




Locksmiths

Residential
Projects

Melville Court, London



Repair to leaking joints
under bath



Testing leak for
soundness

Newton Street, Covent
Gardens, London



Installed a new
washing machine

Nina Carroll Way, Kettering,
Northamptonshire



Washer & Dryer being
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ordinance Way, Ashford, Kent



Old boiler before
installation



New boiler being
tested



New room stat
installed

New Street, Wellingborough



Installed new Ideal
boiler



New boiler being tested during
installation



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects


Pied Bull Court, London



New kitchen installed



New bathroom, tiling
& flooring installed



New shower installed

Perie Brook, Stafford



Installation of vinyl
floor (before)



Installation of vinyl
floor (after)



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects

Saint John's Way



Damaged ceiling

Operative cleaning up
after work

Plessey Road, Northumberland

Damaged toilet handle



New toilet handle



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing



Locksmiths

Residential
Projects

Putney Hill, London



Replacing toilet flusher

New flusher to fit into
the toilet basin

Ragsdale Street, Kettering



Sink blocked (before work)



Unblocked sink



Plumbing

Gas &
Heating

Electrics



Cleaning



Roofing

Site
Facilities
Maintenance

Drainage



Refurbishment



Glazing



Locksmiths

Residential
Projects

Ross Road, Wallington, Greater London



Replacing shower
valves



Tidy job, tiles were not
damaged

Rosebery Ave, Malden, London



New flexi hose & earth
bonding installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects


Springfield Road, Luton



Covering carpets to
prevent damage



New sink & toilet
installed



New ceiling installed

Summerville Terrace, London



New oven fan & heating element
installed



Oven left working following parts
replacement



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing




Locksmiths




Residential
Projects

Tranmere Road, London



Installed new boiler
harness



Testing boiler for safety
following the work

Sutcliffe Drive, Leamington
Spa, Warwickshire



Roofing sheets
installed

Trehurst Ave, Birmingham



New boiler installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Warwick Road, London



Old mixer taps



New mixer taps
installed

Woodcote Road, Wallington, London



New shower installed



New shower tested
working



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Washington Square, Kettering, Northamptonshire



New waste pipe
installed



New mixer taps
following replacement



Chemicals added to
central heating system

Welsh Road, West Southam



Installation of new gutters



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects