

Maintenance Portfolio

Obre

www.obre.app | repairs@obre.app

Apollo Drive, Wellingborough, Northamptonshire



New bath plug removed from sealed



New outside stop valve



New bath plug

Calwell Drive, Maidenhead



Crack on roof before repair work



During roof work



Repaired roof & reapplied roof tar

Ground floor flat, Castle Road, London



New bath panel



New bathtub & new tiles installed

Cavendish Mews, Heene Place, Worthing



Rusty old radiator



Old & new radiators



New radiator

Claygate Hare Lane, Esher, Surrey



Old cartridge removed



Installed new cartridge



Testing new system

Coventry Road, Rugby, Warwickshire



Old snapped overflow pipe



The overflow pipe being installed



New cold-water tank overflow pipe installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Hinkler Road, Southampton



Installed new PVC
Entrance door



Installed new Full
Bathroom




Installed new carpet &
new PVC window

Joyce Silver Court, Addington Road, Wellingborough



Adjusted & repaired
the PVC window



New door lock
installed



New mixer tap
installed

Kingfisher Drive, Maidenhead, Windsor




Testing boiler PCB

Longfellow Road, Worcester Park, London



Installed new bath,
tiling and sealed



New shower mixer tap



Full repointing of the
roof



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Matthias Court, Church Road, Richmond



New sink trap & waste connectors



New earth bonding & WM inlet hose



New under sink waste trap installed

Midleton Road, New Malden



Installed new condensing pipe



New boiler condensing trap installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Oaks Cottage, George Street, Wellingborough



Damaged PVC door lock




Installed new PVC door lock



Restoring old solid wooden door

Palace Road, London



New door lock installed



Slide door adjusted & tested



Installed new wardrobe shelve



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Savoy Close, Birmingham



Dust sheet installed
before painting




Newly painted
bedroom

Smallwood Road, London



Old fence



New fence installed



Garden left clean after
fence installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects


Southolm Street, Southwest, London



New PVC window installed



New mixer taps installed



New bath screen installed

Tithelands, Harlow, Essex



Installed new PRV valve



Tested boiler after re-filling system

Wilton Court, Westmount Close, London



Old boiler before replacement



Installed new boiler

Woodland Rise, London



Installed 50cm wide fridge, with new power point



Our operatives in full PPE & mask

Kings Road, Sudbury, Suffolk




Supplied & installed
new range cooker

Middleton Way, Crawley, West Sussex



New shower handle
railing installed



Shower thermostatic
valve repaired



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ennerdale Close, Sutton, London



New integrated freezer



Testing new fridge working

Ardmore Lane, Buckhurst Hill, Essex

Brolly Works, Allison Street, Birmingham



New electric hob installed



Installed new sink & mixer tap



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Chancellor's Road, London



Installed new bath
mixer taps

Fullers Mead, Harlow, Essex



New fire door installed

George Street, Rushden,
Northamptonshire



Installed a new shower



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects

Sheppeys, Haywards Heath,
West Sussex




New fence installed

Pavior Road, Nottingham




New shower room
door & rubber installed

Lancaster Ave, Mitcham,
Greater London



New fire door installed

Rawnsley Drive, Kenilworth,
Warwickshire



New garage door
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing




Locksmiths



Residential
Projects

Meridian Court, Fernleigh Close, Croydon



Replacing bath overflow waste pip



New trap installed

Cambie Crescent, Colchester

Mill Green, Congleton, Cheshire



Supplied & installed new oven



Supplied & installed new toilet & lino flooring



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential Projects

Dale Lodge, Shepherds Hill, Highgate



Painted living room
after repairs to walls

Turpin Close, Gainsborough,
Lincolnshire



Upgrade gas meter outlet
pipework from 15mm to 22mm

Boundary Close, Doncaster



Installed new window



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Barley Ponds Road, Ware, Hertfordshire



Gardening work



Repaired entrance wall

Bartok Close, Basingstoke

Broadfield Road, London



Repair to TV aerial



Installed new window rubber and window hinge



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Admiral Way, Hyde, Greater Manchester



Isolation switch replaced



Old faulty electrical shower




New electrical shower installed

Aria House, London



Adjusted & repaired fallen wardrobe



Floor installation



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential Projects

Birley Road, London



Installation of new shower cartridge



New shower controls

Barnmead, Haywards Heath, West Sussex



Old element being removed



New cylinder heating element installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects


Caernarvon Crescent, Milton Keynes



Chimney pointed & new lead flashing



New ceiling following painting



Porch roof skimmed

Brackenbury Gardens, London



Sealed shower room



Installed new bannister



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Capitol Square, Surrey



Pipework boxing
(before)



Pipework boxing
(after)

Church Hill Road, Surbiton



Installation of a new
expansion vessel

City House, London



Changing toilet parts



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Carlington House, Normanton Road, London



New bathtub toilet & sink installed



New tiles installed



Replacing pipework inside boxing

Eastbourne Road, London



Installed bathtub waste pipes



Installed new compression boiler valves

Garrick Close, London



Old water filter



New water filter installed

Flaxley Close, Lincoln, Lincolnshire



New vented MEGAFLO cylinder installed

Fraser House, Clapham, London



New trap installed under bathtub



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Kelvin Gardens, Croydon



Applied silicon around bathtub



Grouted all bathroom tiles

Eggleton Drive, Wellingborough, Hertfordshire



New alternators installed



New carpet fitted



New pump motor installed

Garth Road, Morden, London



Old boiler before installation



New boiler being commissioned



Flue test on new boiler

Granville Chambers, Wellingborough



New toilet installation



New grouts on tiles



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects


Kettering Road, Kettering, Northamptonshire



Cleaning drains following removal waste



Replaced soil down water pipe



Sealed with cement newly installed soil pipe

Kempsford Gardens, London



Damage caused by another contractor



New tiles installed, grouted & made good



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Lapwing Court, Wesham, Preston



Old expansion vessel removed



New expansion vessel installed



New pump fitted

Mildenhall Road, Birmingham, West Midlands



Damage in underground waste pipe system



Unblocked manhole & tested water running



Inspected all the manholes around the property



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Levy Close, Andover, Hampshire



Damaged tiles replaced



New lead flashing installed

London Road, Redhill, Surrey



Sealed full roof hips

Malthus Path, London



New toilet installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential Projects

Melville Court, London



Repair to leaking joints
under bath




Testing leak for
soundness

Newton Street, Covent
Gardens, London

Nina Carroll Way, Kettering,
Northamptonshire



Installed a new
washing machine



Washer & Dryer being
installed



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ordinance Way, Ashford, Kent



Old boiler before installation



New boiler being tested



New room stat installed

New Street, Wellingborough



Installed new Ideal boiler



New boiler being tested during installation



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects


Pied Bull Court, London



New kitchen installed



New bathroom, tiling
& flooring installed



New shower installed

Perie Brook, Stafford



Installation of vinyl
floor (before)



Installation of vinyl
floor (after)



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths




Residential
Projects

Saint John's Way



Damaged ceiling



Operative cleaning up
after work

Plessey Road, Northumberland



Damaged toilet handle



New toilet handle



Plumbing



Gas &
Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Putney Hill, London



Replacing toilet flusher



New flusher to fit into the toilet basin

Ragsdale Street, Kettering



Sink blocked (before work)



Unblocked sink



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Ross Road, Wallington, Greater London



Replacing shower valves



Tidy job, tiles were not damaged

Rosebery Ave, Malden, London



New flexi hose & earth bonding installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects

Springfield Road, Luton



Covering carpets to prevent damage



New sink & toilet installed



New ceiling installed

Summerville Terrace, London




New oven fan & heating element installed



Oven left working following parts replacement

Tranmere Road, London



Installed new boiler harness



Testing boiler for safety following the work

Sutcliffe Drive, Leamington Spa, Warwickshire



Roofing sheets installed

Trehurst Ave, Birmingham



New boiler installed



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Warwick Road, London



Old mixer taps



New mixer taps installed

Woodcote Road, Wallington, London



New shower installed



New shower tested working



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site
Facilities
Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential
Projects

Washington Square, Kettering, Northamptonshire



New waste pipe installed



New mixer taps following replacement



Chemicals added to central heating system

Welsh Road, West Southam



Installation of new gutters



Plumbing



Gas & Heating



Electrics



Cleaning



Roofing



Site Facilities Maintenance



Drainage



Refurbishment



Glazing



Locksmiths



Residential Projects